



**Got Leaks?**  
**We Got Your Solution!**

## **Pool Water Loss Test:**

Evaporation occurs at the same rate regardless of the volume of water; a bucket will lose a quarter of an inch ( $\frac{1}{4}$ " ) of water at the same rate of evaporation as the pool loses the same quarter of an inch of water

- Fill pool water to normal operating level, usually mid-skimmer or mid-tile
- Shut off Pool Pump (including any other features) and mark the pool water level (pencil or tape works)
- Resume normal pump operation (the auto/manual fill valve should remain off during the test)
- After 24 hours check the level of the pool, if the water level has dropped more than  $\frac{1}{4}$  inch, there is probably a leak

If you have found unexplained water or suspect you have a leak, call Florida Leak Solutions, Inc., for a free consultation (free estimate included) and to schedule a convenient time for one of our professional Leak Detection Technicians to meet with you."

**Phone: 954-734-7133**

**Toll Free: 888-203-5533**

**[www.floridaleaksolutions.com](http://www.floridaleaksolutions.com)**